

New events;

Engine Cylinder Block Crack Repair

ADEN REPAIR SHOP The 1st Repair shop to make the crack repair on the cast iron engine block in Yemen

With the good assistant and supervise from **MESSER Eutectic Castolin Switzerland S.A.**

our repair shop has made the repair on the engine block in two power station in Yemen , the repair has been done with succeed

The engines repaired was 5 MW engines and was been cracked during operation.

For More information's in this regard please do not hesitate to contact us at info@algarmani.com

